








# Mounting instruction

ECOFLEX®10

N-socket, crimp/solder / Art. No. 7370



 <p><b>1.</b> Cut off cable tail right-angled. Move the crimp-cover and the cable sleeve over the cable head.</p>	 <p><b>5.</b> Insert the so prepared cable end into the connector housing as far as it will go (Click). High bend the copper mesh at right angles and cut it with a side cutter. Slide the sleeve up to the stop.</p>
 <p><b>2.</b> Remove 18mm of the outer sheath with a knife.</p>	 <p><b>6.</b> Crimp the crimp jacket with a crimp tool; herewith the copper braid will be trapped between the crimp jacket and the connector housing.</p>
 <p><b>3.</b> High bend the copper mesh at right angles. Remove 6mm of the copper foil and 4mm of the foamed dielectric with a knife.</p>	 <p><b>7.</b> Slide the cable sleeve forward until the kick-off and heat with a hair dryer to let it shrink.</p>
 <p><b>4.</b> Put the inner pin onto the conductor and solder it through the hole.</p>	