Product Data

Hempel's Silic One Tiecoat 27450



Description: Hempel's Silic One Tiecoat 27450 is a high solid, silicone based humidity curing tiecoat for Hempel's

Silic One 77450. Secures adhesion between Hempel's Light Primer 45551 or Hempel's Silic Seal

45441 and Hempel's Silic One 77450.

Recommended use: Also for use as a touch-up and repair of damaged areas. Suitable on glass fibre, steel, aluminium and

plywood.

Availability: Part of European Yacht assortment. Local availability subject to confirmation.

PHYSICAL CONSTANTS:

Shade nos/Colours: 23410/ Yellow. Finish: Semi-gloss Volume solids, %: 67 ± 1

Theoretical spreading rate: 10 m²/l [401 sq.ft./US gallon] - 67 micron/ 2.7 mils

Flash point: 31 °C [87.8 °F]

Specific gravity: 1.2 kg/litre [10.1 lbs/US gallon]

Dry to touch: 3 hour(s), 20°C/68°F

5 hour(s), 10°C/50°F

Fully cured: 2 day(s) , 20°C/68°F VOC content: 230 g/l [1.9 lbs/US gallon]

Shelf life: 1.5 years 25°C/77°F (from date on lid)

The physical constants stated are nominal data according to the HEMPEL Group's approved formulas.

APPLICATION DETAILS:

Application method: Brush/Roller Thinner (max.vol.): Do not dilute.

Pot life: Max. 1 hour after opening the can
Cleaning of tools: HEMPEL'S THINNER 808 (No 3) 08081

Indicated film thickness, dry: 67 micron [2.7 mils]
Indicated film thickness, wet: 100 micron [4 mils]

Safety: Handle with care. Before and during use, observe all safety labels on packaging and paint containers,

consult HEMPEL Safety Data Sheets and follow all local or national safety regulations.

Date of issue: May 2018 Page: 1/2

Product Data

Hempel's Silic One Tiecoat 27450



SURFACE PREPARATION:

Preparation: Ensure all surfaces are clean, oil free and dry. Clean the surface and remove possible oil and grease with a suitable detergent and sand with dry abrasive paper. Carefully remove dust with fresh

Uncoated surface: Apply: 4 - 5 coats (300 µm) of Hempel's Light Primer 45551. If the surface is already primed with a two component primer, abrade and apply 1 coat of Hempel's Light Primer 45551

Existing old antifouling: Surfaces in good condition: Apply: one coat of Hempel's Silic Seal 45441. Allow to dry.

Deteriorated surfaces: Remove old antifouling down to the existing two component primer. Abrade,

clean and dry the surface. Apply: one coat of Hempel's Light Primer 45441.

PRODUCT APPLICATION: Method: Apply 1 coat of the product. Tiecoat application onto Hempels' Light Primer

> 45551/Hempel's Silic Seal 45441 is a maximum 4 hours / minimum of 2 hours at 20°C; maximum 8 hours / minimum 4 hours at 10°C. Pour paint into paint tray and replace lid. Fully load roller/brush with paint and apply with soft easy strokes to ensure complete coverage. Paint runs can be evened out

before the paint dries.

Maintenance: If the yellow tiecoat is visible or may be damaged: Carefully remove all loose coating. Clean the damaged area with Boat Shampoo, rinse with fresh water and allow to dry. Apply: one coat of Silic One Tiecoat onto a slightly larger area than the damaged surface. Apply: one coat of Silic One onto a slightly larger area than the previously applied Silic One Tiecoat. Apply: one coat of Silic One to entire underwater surface. For larger and deeper damage refer to the Repair Section in the Silic One

System brochure, The Hempel Paint Manual or hempelyacht.com.

APPLICATION CONDITIONS: Use only where application and curing can proceed at temperatures above: 10°C/50°F. The surface

> must be completely clean and dry at the time of application and its temperature must be above the dew point to avoid condensation. Do not apply in direct sunlight. In confined spaces provide adequate ventilation during application and drying. The paint is sensitive to humidity. Do not open the can until

just before application.

RECOMMENDED DETERGENT: HEMPEL'S PRE-CLEAN 67602

HEMPEL'S LIGHT PRIMER 45551 or HEMPEL'S SILIC SEAL 45441. PRECEDING COAT:

SUBSEQUENT COAT: HEMPEL'S SILIC ONE 77450.

REMARKS: If the existing primer is a non-epoxy primer or a one component primer, then the primer must be

removed, and the surface must be primed with 4 coats of HEMPEL'S LIGHT PRIMER 45551. (A one

component primer cannot be overcoated with a two component primer).

It is of utmost importance that thorough protection and cleaning procedures are followed before and

after the application. After application clean all equipment very thoroughly.

Stirring: Stir product well before use..

Storage Conditions: Exposure to air and temperature variances should be avoided. Avoid direct sunlight. Keep containers

tightly sealed. Store at temperatures: 5°C/41°F - 35°C/95°F.

Overcoating: If the overcoating interval is exceeded between Hempel's Light Primer 45551 / Hempel's Silic Seal

45441 and Hempel's Silic One Tiecoat 27450, then a new coat of the primer must be applied.

Hempel's Silic One Tiecoat 27450 Note:

ISSUED BY: HEMPEL A/S 2745023410

This Product Data Sheet supersedes those previously issued.

For explanations, definitions and scope, see "Explanatory Notes" available on www.hempel.com. Data, specifications, directions and recommendations given in this data sheet represent only test results or experience obtained under controlled or specially defined circumstances. Their accuracy, completeness or appropriateness under the actual conditions of any intended use of the Products herein must be determined exclusively by the Buyer and/or User.

The Products are supplied and all technical assistance is given subject to HEMPEL's GENERAL CONDITIONS OF SALES, DELIVERY AND SERVICE, unless otherwise expressly agreed in writing. The Manufacturer and Seller disclaim, and Buyer and/or User waive all claims involving, any liability, including but not limited to negligence, except as expressed in said GENERAL CONDITIONS for all results, injury or direct or consequential losses or damages arising from the use of the Products as recommended above, on the overleaf or otherwise. Product data are subject to change without notice and become void five years from the date of issue.