

## ■ BIGSTONE DISPLAY


### Turning on the display

Press the "M" button (1) left of the display to turn electric circuit on. Display is turned on and a menu appear.

1 = On/off button


2 = Motor support up and lights

3 = Motor support down




### Switching bicycle lights on and off

Press the "+" button (2) ±2 seconds to turn on lights. A symbol will appear on the display. Press button (2) again for ±2 seconds to turn off.



### Switching between the 9 levels of electric support

The electric support has 9 positions. Current support setting is shown at the bottom left of the display. You can switch between these settings by briefly pressing the "+" (2) or "-" (3) button.



### Other options

Briefly pressing the "M" button in succession will scroll through various data at the bottom of the display:


(J) - Total Km/Miles (ODO)

(K) - Trip mode (TRIP)

(L) - Cycled time (TIME)

(M) - Maximum speed (MAX)


**Attention:** Reset Trip, Time and Maximum Speed by pressing and holding the (-) button.



### Thumb lever

By pushing the lever (A) forward when stationary, the walk assist will be activated (which give support up to 6 km/h).

**Attention:** Walk assist does not work when support mode is set to '0'. Using the lever while pedalling, the support will go to its maximum speed of 25 km/h.



### USB-port

Below the display is a USB port (A) where you can charge, for example, your smartphone or navigation device while cycling. You must activate the port by pressing the "M" and "+" buttons for a few seconds.

