

SIZE SPECS.


MEN

HOW TO MEASURE

CREWNECK:

Width: measure from the left to the right under the arms (A)

Length: measure from the highest shoulder point to the bottom of the crewneck (B)



SIZE	S	M	L	XL	XXL
LENGTH (A)	53	55,5	58	60,5	63
LENGTH (B)	70	72	74	76	78