




4




5



6











HUNDOS®



HUNDOS®

ASSEMBLY INSTRUCTIONS



	Maat S	Maat M	Maat L
A	1x	1x	1x
B	2x	2x	2x
C	1x	1x	1x
D	1x	1x	1x
E	1x	1x	1x
 1 M6 x 20mm	12x	12x	12x
 2 M6 x 40mm	4x	4x	4x
 3 M5 x30mm	2x	2x	2x
 4	1x	1x	1x
 5	2x	2x	2x
 6	12x	12x	12x
 7	2x	2x	2x

